

11 09:54	SU 20090630095408.png	Created by spsop from cwo-ccc-a7lc
12 10:25	We switch off manually all power converter CN Rocs.BA4.RBI.81607 (String:1) -> OFF Rocs.BA4.RBIH.400107 (String:1) -> OFF Rocs.BA4.RBIH.400107 (String:1) -> OFF Rocs.BA4.RBIH.400309 (String:1) -> OFF Rocs.BA4.RCIBV.400293 (String:1) -> OFF Rocs.BA4.RCIBV.400097 (String:1) -> OFF Rocs.BA4.RCIBV.400097 (String:1) -> OFF Rocs.BA4.RCIDV.400097 (String:1) -> OFF Rocs.BA4.RQID.400300 (String:1) -> OFF Rocs.BA4.RQID.400300 (String:1) -> OFF Rocs.BA4.RQIF.400200 (String:1) -> OFF Rocs.BA4.RQIF.400400 (String:1) -> OFF Rocs.BA4.RQIF.400400 (String:1) -> OFF Rocs.BB4.RBI.410010 (String:1) -> OFF Rocs.BB4.RBI.412242 (String:1) -> OFF Rocs.BB4.RBI.412422 (String:1) -> OFF Rocs.BB4.RBIV.412153 (String:1) -> OFF Rocs.BB4.RBIV.412153 (String:1) -> OFF Rocs.BB4.RCIBH.410206 (String:1) -> OFF Rocs.BB4.RCIBH.410206 (String:1) -> OFF Rocs.BB4.RCIBH.4110806 (String:1) -> OFF Rocs.BB4.RCIBH.411206 (String:1) -> OFF Rocs.BB4.RCIBH.411806 (String:1) -> OFF Rocs.BB4.RCIBH.411806 (String:1) -> OFF Rocs.BB4.RCIBV.410306 (String:1) -> OFF Rocs.BB4.RCIBV.4110306 (String:1) -> OFF Rocs.BB4.RCIBV.411506 (String:1) -> OFF Rocs.BB4.RCIBV.411506 (String:1) -> OFF Rocs.BB4.RCIBV.411506 (String:1) -> OFF Rocs.BB4.RCIBV.411506 (String:1) -> OFF Rocs.BB4.RCIBV.411706 (String:1) -> OFF Rocs.BB4.RCIBV.411706 (String:1) -> OFF Rocs.BB4.RQID.411700 (String:1) -> OFF Rocs.BB4.RQID.411700 (String:1) -> OFF Rocs.BB4.RQID.411700 (String:1) -> OFF Rocs.BB4.RQID.411900 (String:1) -> OFF Rocs.BB4.RQID.41200 (String:1) -> OFF Rocs.BB4.RQID.41200 (String:1) -> OFF Rocs.BB4.RQIF.41000 (String:1) -> OFF Rocs.BB4.RQIF.41000 (String:1) -> OFF Rocs.BB4.RQIF.41000 (String:1) -> OFF Rocs.BB4.RQIF.41200 (String:1) -> OFF Rocs.MPSM4140 (String:1) -> OFF Roc	NGS :

13 10:55 SU A. Frasier informed us that he has finished the fan chang	ged in BB4.
14 11:16 SU SU 1000 Turn application with coast1.	spsop from cwo-ccc-a7le
15 11.23 A. Frasier informed us that he has finished the fan chang	
Mains faulty during coast recover. SU SU 20090630114116.png	
	spsop from cwo-ccc-a6lc
TT10 2 PC faulty: Rocs.MAL1001M (String:1) -> FAULT-OFF Rocs.MDLH1028 (String:1) -> FAULT-OFF	spsop from cwo-ccc-a6lc
18 11.47 SII bmu10s is down. We reboot it.	spsop from cwo-ccc-a6lc
MAL1001 and MDLH1028 FAULT_OFF, internal interlock proble SU SU 20090630120018.png 20090630120127.png	⊇m.
> Piquet SPS > PO Ring > Called	spsop from cwo-ccc-a7lc
20 12:06 SU We contact Piquet PO Created by	spsop from ewo-ecc-a7le
> Piquet SPS > PO Ring > On Site	
21 12:38 SU Created by	spsop from cwo-ccc-a7lc

			> Piquet SPS > RF POW > End		
22 12:42		SU	Created by spsop from cwo-ccc-a7lc		
			MOPOS configuration before change		
23 12:49		SU	20090630124948.png Created by spsop from cwo-ccc-a6le		
	╬		After scanning, we obtain this MOPOS delays (look at the capture)		
24 13:04		su	The state of the s		
			Created by spsop from cwo-ccc-a6lc		
25 12 25			We contact Stephen Page about MAL1001 problem with a 0 current when we		
25 13:05		SU	starting it. Created by spsop from cwo-ccc-a7lc		
26 13:28		su	We contact R. Steinhagen about MOPOS calibration. Created by spsop from cwo-ccc-a7lc		
27 13:50		SU	S. Page has modified the ROCS version in TT10. If someone will reboot another ROCS, it will take this new version. So, if a problem with that will happened, contact S. Page.		
	-	Ш	Created by spsop from cwo-ccc-a2lc		
28 13:55		SU	MOPOS scope setting 20090630135618.png Created by spsop from cwo-ccc-a7lc		
			BWS meas. in pulsed mode.		
29 14:19		SU	519V.png		







