
CERN - AB - OP eLogbook 08.09.09 16:45



CERN - AB - OP eLogbook 08.09.09 16:45

Charles Julie is working on Transmitter 1 and 2 (Line 1). We do not retake beam until he's ready	by spsop from cwo-ccc-a7le by spsop from cwo-ccc-a7le
14 09:00 We do not retake beam until he's ready Created to orbits 15 09:14 Property of the control of the	
Orbits 15 09:14 Orbits In the state of th	
15 09:14	V1_14000.csv
Created I	by spsop from cwo-ccc-a6lc
Trim problem. Greg called.	
09:19:38 - Revering settings to '2009-07-13 12:51:26.781' 09:19:39 - Revert Failed: cern.cmw.AccessDenied cannot be cast to cern.japc.ParameterException java.lang.ClassCastException: cern.cmw.AccessDenied cannot be cast to cern.japc.ParameterException at cern.lsa.exploitation.domain.DriveHardwareParameterException.getParameterException(DriveHardwareParameterException)	ception.java:60)
17/09.44 Greg fixed the TRIM problem.	
Created t	by spsop from cwo-ccc-a6lc
Created I	by spsop from cwo-ccc-a6lc
19 10:24 COMPASS call to restart the dipGwExp process on the cs-ccr-cmw2.	by spsop from cwo-ccc-a6lc
20 10:31 Access to 811 for some maintenance work	by spsop from cwo-ccc-a6lc
Left Access console did not want to startup the SPS Zora access software correctely. After a startup the application of the constant of the Access Server. After the restart it works are consoled in the constant of the Access Server. After the restart it works are consoled in the constant of the Access Server.	plication
Christoph Mugnier (PO) will do some measurements tomorrow at 11:00 to do some measurements on the Imin. This about half an hour.	s will take by spsop from cwo-ccc-a7lc
Together with Nicolas Gilbert we removed the padlock for the roof access on the right side of building 3191 magnet repair workshop). Nicolas Gilbert placed a personal padlock for the time being. The padlock which was be opened with the LS2K8 key (tag marked with 'SPS Operations padlock'. The roofaccess is ment for the main buildings cooling system.	(SM12 - LHC s placed could
Some losses due to a noise generator on damper.	-y -poop Hom ewo-ecc-dole
To remove the noise switched on LHC2 and COAST1: disable SX.RF.7-6-8 (tdamper noise on / tune meas. chirp off coast) enable SX.RF.7-7-1 (tdamper noise off / tune meas. chirp on coast)	
	by spsop from cwo-ccc-a7lc
25 11:19 Prepared access to 118 for Sylvain Girod. P42/P0 is in already in access. Created by	by spsop from cwo-ccc-a7lc
26 13:44 Added LHC2 configuration to the old LHC-Larger page 112.	by spsop from cwo-ccc-a7lc
FAULTS	^
# Group Fault Element Description Begin End Duration	





NO FAULT

